

100

Step 104

Measure an Attribute
of the Input Signal

Step 108

Use the Open Loop
Control System

Step 112

Are the
Control
Parameters
Satisfied?

No

Yes

Step 116

Pass Control to the Closed loop
Control System

Step 120

Use the Closed Loop
Control System

FIG. 1




FIG. 2



400




FIG. 4




Fig. 5




Fig. 6